



Firmware for SL60-401 / SL60-501 / SL60-4010

Known bugs

To: Whom it may concern
Attachments: -

Firmware Version 1.06 (Rev 923)

- SNMP: SNMPv3 does not work properly (still in beta status)
- SNMP: When network interface is down, the SNMP object "ifSpeed" does return 10 Mbps
- Web GUI: On the service page, the event log does report incorrect information
- Web GUI: On the statistics page, the amount of errored packets of the air interface remains zero, even when errors occurred.

Firmware Versions 1.01 (Rev 634) and 1.03 (Revision 648)

- SNMP: SNMPv3 does not work properly (still in beta status)
- Web GUI: Missing reset button on statistics page
- Web GUI: Wrong "Network Datarate" displayed on overview page
- SNMP: SNMP object "ifSpeed" of Ethernet interface does return wrong value

Firmware Version 0.81 (Rev 543)

- Setting the terminal to factory default, might set wrong default password and username (sl60 / admin instead of admin / sl60)
- If VLAN is enabled the default gateway is not set properly.
- SNMP: No replies from SNMP objects of the interfaces group MIB (IF-MIB)
- Web GUI: Missing reset button on statistics page
- Web GUI: Even though the link is ok, the remote traffic light intermittently displays red